



NICKEL
SYSTEMS


Hex Head Machine Screws



+1 (610) 904-8616

sales@nickel-systems.com

www.nickel-systems.com



Nominal Size	Basic Screw Diameter	Regular Head			Large Head			H							
		A		Minimum Across Corners	A		Minimum Across Corners								
		Width Across Flats			Width Across Flats										
		Max.	Min.		Max.	Min.									
1	0.0730	0.125	0.120	0.134	0.044	0.036						
2	0.0860	0.125	0.120	0.134	0.050	0.040						
3	0.0990	0.188	0.181	0.202	0.055	0.044						
4	0.1120	0.188	0.181	0.202	0.219	0.213	0.238	0.060	0.049						
5	0.1250	0.188	0.181	0.202	0.250	0.244	0.272	0.070	0.058						
6	0.1380	0.250	0.244	0.272	0.093	0.080						
7	0.1510	0.250	0.244	0.272	0.093	0.080						
8	0.1640	0.250	0.244	0.272	0.312	0.305	0.340	0.110	0.096						
10	0.1900	0.312	0.305	0.340	0.120	0.105						
12	0.2160	0.312	0.305	0.340	0.375	0.367	0.409	0.155	0.139						
14	0.2420	0.375	0.367	0.409	0.438	0.428	0.477	0.190	0.172						
1/4	0.2500	0.375	0.367	0.409	0.438	0.428	0.477	0.190	0.172						
5/16	0.3125	0.500	0.489	0.545	0.230	0.208						
20	0.3200	0.500	0.489	0.545	0.230	0.208						
24	0.3720	0.562	0.551	0.614	0.295	0.270						
3/8	0.3750	0.562	0.551	0.614	0.295	0.270						
7/16	0.4375	0.625	0.610	0.682	0.348	0.321						
1/2	0.5000	0.750	0.735	0.820	0.400	0.367						

Notes: (1) All dimensions are in inches. (2) For common sizes, hex head machine screws are typically stocked in fractional length increments of 1/16 in. for screws up to 1-1/2in. long, 1/8 in. for screws over 5/8 in. through 1-1/2 in., and 1/4 in. for screws over 1-1/2in. long. (3) For more information, refer to ASME B18.6.3-2024.